



PRESS RELEASE

Bee Line Company
2700 62nd Street Ct.
Bettendorf, IA 52722
www.beeline-co.com

Public Relations Contact: Tricia Kane
Director of Sales & Marketing
Phone: 563-332-4066 ext 364
Fax: 563-332-6517
Email: tkane@beeline-co.com

Bee Line 3D Optical Frame Assessment System

Generate a Before & After Report of Truck Frame Damage

BETTENDORF, IA — January 30, 2018 — Bee Line has introduced the OM8000 Optical Frame Assessment System.

This exclusively designed system features a single infrared camera that captures the initial conditions of a damaged frame, allowing the operator to determine what corrective measures need to be taken. The camera, which has a self-contained light source for accuracy, connects with retro-reflective targets mounted with self-centering frame gauges that accurately represent vehicle conditions.

The 3D system is capable of accurate initial condition reporting, dynamic tracking of corrections as they are made and final condition reporting relative to appropriate specification tolerances.

How the system works:

- Enter specific vehicle data and capture “before” pictures of the damaged areas to upload to diagnosis software.
- Properly mount the frame gauges on the truck rails. New lock design secures the gauges to the frame, ensuring that they sit 90-degrees to the frame. Focus the camera and capture coordinates of all points on all targets.
- The 3D system diagnoses and illustrates the condition(s). Results are documented and a report is generated showing before and after photos and frame assessment data.

For more information, visit www.beeline-co.com.

Bee Line — Over 100 Years’ Experience. Proven Results.